


Department	Total	Target per Day	Current MTD	% Compliance	% Compliance Project	
Community	7	0.2	7	100%	100%	●
Security	35	1.2	35	100%	100%	●
Process Plant Operation	483	16.1	473	98%	98%	●
Tailing Management Facilities	52	1.7	49	94%	94%	●
Commercial	325	10.8	290	89%	89%	▲
Mine Maintenance	200	6.7	172	86%	86%	▲
Roads & Utility	29	1.0	24	83%	83%	▲
Mine Technical Services	5	0.2	4	80%	80%	▲
Environmental	39	1.3	31	79%	79%	▲
Human Resources	841	28.0	653	78%	78%	▲
Engineering Services	26	0.9	18	69%	69%	▲
Mine Operation	96	3.2	60	63%	63%	▲
Punta Rincon	501	16.7	312	62%	62%	▲
Process Plant Engineering	297	9.9	149	50%	50%	◆
Safety	13	0.4	5	38%	38%	◆
Construction	166	5.5	63	38%	38%	◆
Finance	1	0.0	0	0%	0%	◆
Total	3116	103.9	2345	75%	75%	



FE Key Performance Indicator
(Compliance Project)



The report only shows the actual number of inspections in the month and compliance based on the number of fire extinguishers each department has.



3116

Total Fire Extinguisher



2420

Total Inspected



685

Overdue Inspection



77.7%

% Inspected



22%

% Overdue

Department	Total	Inspected	% Compliance
------------	-------	-----------	--------------

Community	7	7	100.0%	●
Security	35	35	100.0%	●
Process Plant Operation	483	473	97.9%	●
Tailing Management Facilities	52	49	94.2%	●
Safety	13	12	92.3%	●
Commercial	325	290	89.2%	▲
Mine Maintenance	200	178	89.0%	▲
Engineering Services	26	22	84.6%	▲
Environmental	39	33	84.6%	▲
Roads & Utility	29	24	82.8%	▲
Mine Technical Services	5	4	80.0%	▲
Human Resources	841	666	79.2%	▲
Punta Rincon	501	353	70.5%	▲
Mine Operation	96	60	62.5%	▲
Process Plant Engineering	297	151	50.8%	◆
Construction	166	63	38.0%	◆
Finance	1	0	0.0%	◆
Total	3116	2420	77.7%	

Fire Extinguisher Inspection Map (Current Month)

